THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEASE UNDER DOD DIRECTIVE 5200.20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLUSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.



185712

DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

AGDA (M) (12 Aug 69)

FOR OT UT 692243

18 August 1969

SUBJECT: Operational Report - Lessons Learned, Headquarters, 165th

Aviation Group, Period Ending 30 April 1969

SEE DISTRIBUTION

1. Subject report is forwarded for review and evaluation in accordance with paragraph 5b. AR 525-15. Evaluations and corrective actions should he reported to ACSFOR OT UT, Operational Reports Branch, within 90 days of receipt of covering letter.

Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

1 Incl as

inneth G. Nicklam KENNETH G. WICKHAM Major General, USA

The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Air Defense School

US Army Aviation School

US Army Combat Surveillance School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

US Army Ordnance School

US Army Transportation School

UNCLASSIFIED REPORT

DISTRIBUTION NO FOREIGN WITHOUT APPROVAL OF Office, Glidef of Staff, US Army ASSISTANT CHIEF OF STAFF FOR FORCE DEVELOPMENT (ARMY) ATTH FOR OT UT. WASHINGTON, D.C. 20316

Copies lurnished: Deputy Chief. of Staff

DEPARTMENT OF THE : 1 HEADQUARTERS 165th AVIATION GROUP APO San Francisco 9638h

AVBACD-C

14 May 1969

SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969,

SEE DISTRIBUTION

1. Section 1 Operations: Significant Activities

a. (U) Command.

- (1) Organizational Changes. During the reporting period there were four major changes in the group organization, (See Inclosure 1, Organizational Chart; and Inclosure 2, Station List;)
- (a) USARPAC General Order Number 114, dated 11 Rebruary 1969, inactivated Headquarters and Headquarters Company, 58th Aviation Battalion (UIC: WGGL AA) and activated and organized Headquarters and Headquarters Company, 165th Aviation Group (UIC: MG7D AA). The effective date of the general order was 17 February 1969. The 165th Aviation Group is organized under MTOE 1-2520, and is assigned to United States Army Vietnam. USARV General Order Number 882, dated 14 March 1969 (effective 17 February 1969) further assigns the group to the 1st Aviation Brigade. There was no change in the group mission.
- (b) USARPAC General Order Number 234, dated 25 March 1969, inactivated the 16th Signal Company (RD OP) (UIC: WGIK AA), effective 1 April 1969.
- (c) 1st Aviation Brigade General Order Number 1667, dated 14 April 1969 reassigned the 120th Assault Helicopter Company (UIC: WAYBTO) from the 12th Combat Aviation Group to the 165th Aviation Group, effective 16 April 1969.
- (d) 1st Aviation Brigade General Order Number 1668 dated 1h April 1969 reassigned the Command Airplane Company (Prov) (UIC: W13P AA) from the 12th Combat Aviation Group to the 165th Aviation Group, effective 16 April 1969.

FOR OT UT 692243 Inclosure AVBACD-C 14 May 1969 SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

- (2) Personnel Changes. The group S-1, Major Elwood J. Becker, Jr., FA, Oh010830 was reassigned within the group. Major R. A. Neuwien, Jr., AR, OF10383h, assumed the duties of the S-1 effective 15 April 1969. Major Jerry W. Manley, Jr., IN, 0530h233, assumed the duties of S-h on 25 February 1969 from Major Raoul J. LeBlanc, TC, Oh025698. A complete listing of the command and staff group is at Inclosure 3.
 - (3) Major Unit Activities.
- (a) Air Traffic Control. There were 2,417,416 recorded operations at 36 Army controlled airfields. The Army flight following system averaged 4859 flights per day for a total of 432,463 for the reporting period. Fourteen ground controlled approach facilities (GCA's) performed 11,473 runs, of which 8,679 were for training and 2,79h were for flights under instrument flight rules.
- (b) Joint Air Operations Group, This headquarters continued to participate in Joint Air Operations Group briefings throughout the reporting period. The mission of the briefing team remained that of acquainting audiences with joint problems and activities involving air traffic control, artillery warming, airspace, and flight information in Vietnam. Audiences briefed included aviators, commanders and staffs at all echelons. Briefings during the period were as follows:

Lates	Commands/Activities
26 Jan - 10 Feb 69	Eleven.major US Air Force units located thoughout Southeast Asia.
3 Mar - 6 Mar 69	Commanders and key staff. members, Headquarters PACAF, USARPAC and PAC FLT
20 Mar - 24 Mar 69	Commanders and key staff members, Headquarters MACV; key staff members, Headquarters USARV; USARV Aviation commanders conference; 165th Aviation Group commanders conference.
9 Apr - Mid-May 69	US Army and Air Force aviation training bases in CONUS.

(c) Joint Vietnam-US Air Coordination Committee (ACC). This headquarters participated as a working member of the Joint Airfield Survey Subcommittee of the ACC during the period of this report. Subcommittee membership includes the Directorate of Civil Aviation (DCA), the Vietnamese Air Force (VNAF), the Civil Aviation

AVBACD-C 14 May 1969

SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

Assistance Group (CAAG), the Military Assistance Command Vietnam (MACV), the US Air Force, US Army and the US Marine Corps. Joint airfield surveys were conducted at Binh-Thuy on 15 Jan 69, Quang Ngai on 26 May 69, Qui Niion on 27 May 69, Dalat/Lien Khuong on 16 Apr 69 and Dalat/Cam Ly on 17 Apr 69. The purpose of the surveys is to determine deficiencies at joint use airfields and make recommendations to the appropriate agency for the overall improvement of air navigation, airfields, ground aids, terminal and enroute air traffic control, flight information, communications and navigational aids. Surveys to date have noted the following descrepancies:

- (1) Obstacles were located in sirfield clear areas in violation of MACV and ICAO standards.
- (2) Most mirfields require engineer effort to up-grade runway, taxiway and ramp surfaces. Most drainage and access roads were inadequate.
- (3) Communications between airfield control towers and air traffic control agencies was found to be inadequate in many cases.
- (4) Some airfields do not have crash rescue equipment and trained crash rescue personnel.
 - (5) Marking/painting at airfields was inadequate.
 - (6) Current weather information was unavailable in some locations.
- (7) Uncontrolled pedestrian and vehicle traffic was a constant problem at all airfields.
- -(4). Quarterly Commanders Conference, The quarterly commanders conference was held on 25 Mar 69, in the USARV auditorium, with 36 unit commanders present. Attendees were br. fed by the group commander and staff on internal group matters. In addition, the Joint Air Operations Group briefing team presented the JAOG educational briefing (reference para 3b above). Of particular benefit to the commanders was a discussion period covering mutual problems and local solutions.
- (e) Angual General Inspection Results. During the period 18-22 Feb 69, the group received its first Angual General Inspection (AGI) by HQ, USARV. Units inspected included Headquarters and Headquarters Company, and the 125th Air Traffic Company. The comments of the inspecting team were generally very favorable. The overall rating of the group was satisfactory.

AVBACD-C

14 May 1969

SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

b. (U) S1 (Personnel).

(1) Losses and gains maintained an operational balance during this quarter. Authorized and assigned personnel strengths as of 2 May 1969 are:

	Authorized	Assigned
Off	120	130
WO	75 1473	56 1563
E4	1473	1563

- (2) Moralo: Excellent (\hat{c} month extensions for the months: Fob = 25, Mar = 35, Mpr = 17).
 - (a) Disciplino: 7 Court-Martials and 20 Article 15's
 - (b) Roenlistments:

Month		Re Ups	% of Re Ups
	Eligible		
Feb	32	6	18;7
Mar	19	2	11.1
\mathbf{x} Ç Λ	31.	0	0

- (c) Mail: No Problems Areas.
- (3) Awards and decorations: See Inclosure 4.
- c. (U) S2 (Intelligence).
- (1) The following are figures pertaining to personnel security for this reporting period.
 - (a) Clearances granted 10 CONFIDENTIAL and 68 SECRET.
 - (b) Clearances validated 59 SECRET and 13 TOP SECRET.
- (c) There is one unfavorable security action (suspended access) currently swaiting results of investigation.
 - (2) Total personnel socurity administrative actions ~ 151.

AVBACD-C SUBJECT: 14 May 1969

Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

d. (U) S-3 (Operations).

- (1) Tactical Air Traffic Control Teams (TATCT) were deployed to support airfields at Camp Eagle, Lai Khe, Torle Cham, and Tay Ninh (West). See Inclosure 8.
- (2) The current status of Project Commando Indian, collocation of US Army flight following facilities with US Air Force traffic regulation centers, is unchanged. Completion of the project is pending movement of Army Coastal Center to the facility at Hon Tre Island. At the close of the period, this action was being reevaluated in light of administrative, logistical and operational problems posed by relocation of the entire center off the mainland.
- (3) In response to a requirement for additional flight following coverage in forthern I Corps Tactical Zone, a flight following station was installed at Pin Bai. See Inclosure 8.
- (4) The Group GCA plan was approved by HQ, USARV 9 Mar 69 (Inclosure 7). Implementation began in March and all permanently sited GCA equipment will be in position by June 69. Seasonal GCA equipment has been placed at Cu Chi and Phu Loi. Lai Khe will receive its equipment in the very near future. There are currently no contigency requirements for GCAs.
- (5) Flight evaluations were conducted on 23 Army mirfields/heliports (See Inclosure 5). This program continues to be hampered by the lack of mircraft.

e. (U) S3 (Training).

- (1) The GCA school at Long Thanh has graduated 20 controllers during the period from 31 Jan 69 to 30 Apr 69. Of the 20 controllers graduated, 4 were from the 101st Airborne Division, 3 were from the 1st Cav Div and the remainder were from ASD GCA sections and the 125th AT Co.
- (2) The first class of the Diesel Generator Maintenane School for CY 1969 commenced on 20 April 1969 and graduated 8 personnel on 26 April 1969. The school will continue until all new generator mechanics (52B20) in the group have completed the course of instruction. The POI for the course consists of 48 hours of conference and practical work on the 30KW. generator. This curriculum includes instruction on operator maintenance and PLL procedures. The Decca diesel generator technical assistance team has been tasked with organizing and operating the school, with support from the 313th ASD.

AVBACD-C SUBJECT:

Street Characteristics of the Characteristics

operational Report of Headquarters 165th Aviation Group for Pation Ending 30 April 1569.

- (3) Training inspections were conducted at all aviation support detachments except the 322nd aviation support detachment at Quam Loi and the 314th Aviation Support Detachment at Lai Khe. In the majority of cases the problem areas have been minor mistakes in completion of USARV form 389 (ATC Training Record), personnel not facility rated, facility training manuals not in use and TM's not current.
- (4) Training assistance has been given to the eviation support detachments with the following results:
- (a) Facility training manuals are now in use at all but lh eviation support detachments. Those are expected to be completed within the very near future.
- (b) There have been 92 controllers facility rated during the period from 1 Feb 59 to 30 Apr 69. At present 16 Aviation support datachments their facility chiefs facility rated. This will expedite the group fac. ty rating of additional controllers. The facility training manual and . a group facility rating guide are proving to be invaluable aids to facility rating personnel, and improving the proficiency of personnel are presently facility rated.

f: (U) Sh (Logistics).

- (1) Equipment and supplies are being received through supply channels at an improved rate.
- (2) The 6,000BTU/400 cycle air conditioners that were obtained by special USARV authorization are being directly exchanged with the using units to replace inoperable air conditioners.
- (3) USARV has authorized additional radios to be used as aviamics float. These radios have been requisitioned.
- (4) Extensive generator repair is being conducted on site by the 165th Aviation Group civilian diesel generator technical assistance personnel.
- (5) All PU 126 motor generators are being turned in for repair through the S-4 officer, Coordination has been effected with the 378th Maintenance Company for this support.

AVBACD-O

14 May 1969

SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

imput to the Tastical Aerodrome Directory, for 36 Army sirflelds and the Army flight following system in Vietnam. In this connection, it is interesting to note that in recent months input to the Tactical Aerodrome Directory from Army units has increased from 25% to 32% of the total information input. The increase is substantially the result of the efforts of this section.

(3) During the week of 7-14 April 1969, the group was visited by Mr. Donal Zellmer, flight information specialist with the US Army Flight Information Detachment (Pacific). The purpose of the visit was to coordinate and correla certain types of information common to the Tactical Accordance Directory and the RVN Frequency Publication.

i. (U) Safety.

(1) The addition of two subordinate units and their aircraft has substantially increased the assident exposure rate for the group. During the reporting period there was one accident involving a UH-IB sircraft of the 120th Assault Helicopter Company. The group accident statistical rate is as shown below.

	Feb - Apr	FY
HHC	0	0.
125th AT Co	0	52,6
120th AHC	38.1	17.6
CAC	0	0

(2) The fixed year cumulative rate for the group is 36.3, and includes hours flown by the 16th Signal Co, CAC, and the 120th AHC(the last two for the period from 15 April 1969).

j. (U) Signal.

(1) The first class of school-trained AN/TSQ-75 aviones repairmen (MOS 35L) arrived in March. The training of these repairmen appears to be adequate. After a brief orientation on in-country procedures, they were assigned to Eviation Export detachments. Subsequent reports on their performance are very encouraging. However, the program of instruction on the AN/TSQ-75 should be changed to incorparate lessons learned in Vietnam (See Section 21).

AVBACTURE - Sport of Hondayartana 165th Add at an Group

SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

input to the Tastical Accordance Directory, for 36 Army similarly said the Army flight following system in Vietnam. In this connection, it is interesting to note that in recent months input to the Tactical Accordance Directory from Army units has increased from 25% to 32% of the total information input. The increase is substantially the result of the efforts of this section.

(3) During the week of 7-14 April 1969, the group was visited by Mr. Donal Zellmer, flight information specialist with the US Army Flight Information Detachment (Pacific). The purpose of the visit was to coordinate and correla cortain types of information common to the Tactical Aerodramo Directory and the RVN Frequency Publication.

1. (U) Safety.

THE PROPERTY OF THE PROPERTY O

(1) The addition of two subordinate units and their aircraft has substantially increased the accident exposure rate for the group. During the reporting period there was one accident involving a UH-IB aircraft of the 120th Assault Helicopter Company. The group accident statistical rate is as shown below.

	Feb - Apr	FY
HHC	0	o .
125th AT Co	0	52,6
120th AHC	38.1	17.6
CAC	0	0

(2) The fiscal year cumulative rate for the group is 36.3, and includes hours flown by the 16th Signal Co, CAC, and the 120th AHC(the last two for the period from 15 April 1969).

j. (U) Signal.

(1) The first class of school-trained MN/FSQ-75 avionics repairmen (MOS 35L) arrived in March. The training of these repairmen appears to be adequate. After a brief orientation on in-country procedures, they were assigned to eviation apport detachments. Subsequent reports on their performance are very encouraging. However, the program of instruction on the AN/FSQ-75 should be changed to incorporate lessons learned in Vietnam (See Section 21).

AVBACD-C
SUBJECT: Operational Report of Headquarters 165th dation Group
for Period Ending 30 April 1969.

- (2) The plan for a command/NOTAM teletype net is still being staffed by lst Aviation Brigade (ref: ORLL, this headquarters, dtd 15 Fab 69). The SEANC circuit to this headquarters is installed and operational.
- (3) The primary means of communication presently used by this headquarters to subordinate units is an HF SSB voice net. This is tasked beyond practical capabilities by its size. It consists of thirty-six reporting stations, handling approximately 100 messages per day. Average monthly participation for all stations is approaching 95%.
- (4) The contralized control of all ATC radio frequencies by this headquarters has proven to be very successful. Problems still exist in Frequency Modulated (FM) frequencies which, through experience and further coordination with frequency managers are expected to be allewiated (See Section 2.).
- (5) There has been notable progress on the availability rate of GCA radars during the period of this report. Through the concentrated efforts of the Flight Check and Signal Sections of this headquarters, the support of the 31th GG Group and the ITT Chifillan technical assistance personnel, the down time of GCA equipment has decreased and reliability has improved significantly.
- (6) The modification of the AN/TRN-25 non-directional beacons can now be increased with the arrival of 74 modification kits. The AN/TRN-25 beacons will be installed as back-up for all AN/GRN-6 beacons within the next 30 days.
- k, (U) Headquarters Commandant. On 7 April 1969, construction was initiated to upgrade the onlisted men's biliets and Headquarters Company buildings to more permanent, tropical-type buildings. The compartmention was performed by a post engineer contractor. The completion of the project makes available improved living conditions for enlisted personnel.

AVBACD-C 14 May 1969 SUBJECT: Operational Report of Headquarters, 165th Aviation Group for Period Ending 30 April 1969.

- 2. Section 2, Lessons Learned: Commander's Observations, Evaluations, and Recommendations.
 - a. (U) S1 (Personnel). None.
 - b. (U) S3 (Operations). Shortage of AN/TSQ-70A Towers.
- (1) ObsERVATION. There is a critical shortage of AN/TSQ-70A control towers in Vietnam.
- (2) EVALUATION. Currently there are twenty-two control towers, AN/TSQ-70A, assigned to this headquarters, all operational and committed. During the past three months there have been requests for permanent ATC tower support at five locations. Each of these requests is pased on a valid requirement for an AN/TSQ-70A tower. At present, these requirements are being satisfied either by locally fabricated, makeshift radio equipment or by a Tactical Air Traffic Control Team (TATCT) provided on a temporary basis and subject to withdrawal on short notice. Traffic density at many airfields dictates that helicopter and fixed wing operations be separated, often requiring two control towers. In addition, the two airmobile divisions are short a total of seven control towers, AN/TSQ-70A. Accordingly, this headquarters must support their tactical operations with TATC teams which ordinarily would be employed in support of units which have no ATC assets. The total requirement is for 17 AN/TSQ-70A towers, including the seven for the two airmobile divisions.
- (3) RECOMMENDATION. That seventeen additional control towers AN/TSQ-70A be obtained to support increased air traffic control requirements in Vietnam.
- (4) COMMAND ACTION. A letter is being forwarded to USARV requesting the required additional control towers.
- c. (U) 53 (Training). Use of AN/TPX-44 for Aircraft Identification.
- (1) OBSERVATION. A majority of GCA controllers are failing to use the IFF/SIF system because they either are not familiar with the procedures to be used or they lack confidence in their proficiency with the equipment.
- (2) EVALUATION. The AN/TPX-44 can and should be used to locate and identify quickly and accurately aircraft requesting radar services. Many aviators will not make practice GCA's because of the excessive time required for radar identification using identification turns. Use of IFF/SIF is also greatly preferred for the purpose of more rapid and positive identification under actual instrument conditions as well as in areas of excessive traffic congestion.

AVEACD-C 14 May 1969 SUBJECT: Operational Report of Headquarters, 165th Aviation Group for Period Ending 30 April 1969.

- (3) RECOMMENDATION. Recommend that the ATC Department, USAAVNS, stress the use of the AN/TPX-44 in GCA training.
 - (4) COMMAND ACTION.
- (a) All units with GCA equipment have been instructed to conduct unit training in the use of IFF, and to use this capability to the maximum extent. Group policy requires the AN/TPX-44 to be fully operational (antenna turning) anytime the GCA is on the air.
- (b) The 165th Aviation Group GCA School at Long Thanh has adjusted its POI to emphasize the use of IFF.
 - d. (U) S2 (Training). None.
 - e. (U) S4 (Logistics). Repair of 30KW Generators.
- (1) OBSERVATION. Direct Support Units are salvaging 30kW generators which can be easily repaired.
- (2) EVALUATION. Frequently when a 30kW generator has been turned in to a DSU, the DSU has classified the generator as salvage. The DSU then cannibalises the generator to repair others. In nearly all such cases the generator has been repairable, provided the necessary repair parts were on hand. Had parts been available, the generators concerned could have been returned to service rapidly and with minumum adverse effect on ATC operations.
- (3) RECOMMENDATION. That DSU's take appropriate action to stock critical repair parts for 30KW generators, so as to insure more responsive maintenance support.
 - (4) COMMAND ACTION.
- (a) A concentrated program is in progress to verify that units have turned in density listings and are requisitioning PLL's. This will be a subject of continuing emphasis on command visits and inspections.
- (b) A standard procedure has been established whereby one of the group civilian contract diesel generator mechanics will inspect each generator being turned in for repair and advise the unit commander on its repairability.
 - f. (U) S3 (Organisation). None.
 - g. (U) Sl (Information). None.
 - h. (U) Flight Check. None.

AVENCE—C 14 May 1969 SUBJECT: Operational Report of Headquarters, 165th Aviation Group for Period Ending 30 April 1969.

- i. (U) Signal (Communications).
- (1) School Trained Avionics Equipment Revairmen.
- (a) OdSERVATION. School trained Avionics Equipment Repairmen (MOS 35L) oriented toward maintenance of AN/FSQ-75 Air Traffic Control Equipment are arriving in country with sufficient skills to adequately maintain this equipment, with exceptions noted below.
- (b) EVALUATION. The Program of Instruction of the 102-35L20 course conducted at Southeastern Signal School, Fort Gordon, Georgia, is adequate for CONUS installations. Operational and climatic conditions have necessitated changes in procedures for Vietnam. Tuning procedures developed for the TV-36 and TU-9 transmitters and the replacement of C-58 and C-76 capacitors, high failure rate parts, have been incorporated into in-country orientations for new repairmen.
- (c) RECOMMENDATION. Tuning and parts replacement procedures adopted in Vietnam should be incorporated in the present POI at USASESC for course 102-35120 (AN/FSQ-75 oriented) to decrease the orientation and CJT time required prior to assignment of repairmen to units of the group.
- (d) COMMAND ACTION. At formal recommendation will be forwarded by separate correspondence, setting forth the detailed procedures which are proposed for incorporation in the POI.
 - (2) Use of FM Frequencies.
- (a) OBSERVATION. The frequency spectrum for frequency modulated (FM) radios, 30.00 to 69.95 MHz, is becoming increasingly and excessively crowded in the III Corps Tactical Zone.
- (b) EVALUATION. Many units are using frequencies they have no authority to use. To further complicate the situation, non-US military elements are being issued FM radios and their frequencies are conflicting with other previously authorized frequencies. This problem is increasingly depriving aviation and air traffic control of the benefit of the FM spectrum. Because of the line-of-sight characteristics of FM and aircraft calling from the higher altitudes, ATC frequencies must have a clear area of about 100 miles radius from each ground station. The situatuion as it now exists is inherently unsafe and bids fair to become worse as the spectrum becomes increasingly crowded.

AVBACD-C 14 May 1969 SUBJECT: Operational Report of Headquarters, 165th Aviation Group for Period Ending 30 April 1969.

- (c) RECOMMENDATION. More discrete frequencies should be allocated for air traffic control purposes and frequency controls sixeld be substantially strengthened.
- (d) COMMAND ACTION. This headquarters has requested additional FM discrete frequencies for ATC operations and has requested frequency managers to evaluate all cases where multiple-user frequencies interfere with ATC facilities.
 - (3) Parts Manuals for AN/TSQ-75 Equipment.

AND THE RESIDENCE OF THE PROPERTY OF THE PROPE

- (a) OBSERVATION. Lack of direct support and general support parts manuals has presented a repair parts requisitioning and a PLL/ASL problem for the AN/FSQ-75 Air Traffic Control Equipment.
- (b) EVALUATION. The AN/FSQ-75 equipment was received in-country with a package of spare parts for each tower and two direct support "push" packages for all twenty equipment units. These packages were developed by the Federal Aviation Agency (FAA) based on estimates of consumption rates, since no experience data was available. Eight months' experience in maintaining this equipment has provided data from which realistic parts lists and maintenance manuals can be developed.
- (c) RECOMMENDATION. That the experience data accumulated by this group on the AN/FSQ-75 be used by the responsible agency to develop and publish the required technical manuals.
- (d) COMMAND ACTION. This headquarters has initiated repair parts inventories at the various equipment locations and is coordinating a study of the records of demands with the 34th General Support Group.
- (4) Transfer of Direct Support/ General Support Maintenance Responsibility.
- (a) OBSERVATION. The 125th Air Traffic Company, an operating unit of this group, has been providing direct and general support maintenance services on certain equipment, which is beyond the scope of their TOE mission.
- (b) EVALUATION. Supply support of the AN/FSQ-75 and AN/GRN-6 equipment and the maintenance support of the AN/GRN-6 should be removed from the 125th AT Company and assigned to an appropriate DS or GS unit. This would release the 125th AT Company to devote its full capabilities to its mission. The responsibility for providing radio float stock for equipment peculiar to units of this group should also be transferred from the 125th AT Company.

AVBACD-C 14 May 1969 SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969.

- (c) RECOMMENDATION. That responsibility for maintaining and distributing the float stock of ATC and essential support equipment for ATC facilities, systems and components should be assigned to the 34th General Support Group. This includes the float stock on the AN/FSQ-75 equipment and the newly-approved float stock for AN/TSQ-70, AN/TSQ-71, and AN/TSQ-72 equipment. The responsibility for providing repair parts supply on the AN/FSQ-75 equipment and direct/general support maintenance on the AN/GRN-6 equipment should be placed on the 34th General Support Group.
- (d) COMMAND ACTION, Coordination has been established with the 34th General Support Group to transfer the responsibility for maintaining and distributing float stock to this headquarters and the 34th General Support Group. The reorganization of the 34th General Support Group in 1st Quarter FY 70 will facilitate the transfer of the maintenance support function from the 125th AT Company. This reorganization will also enhance the maintenance support on the 14/19Q-75 equipment by providing trained repairmen located in the general support shops of the 34th General Support Group.

James G. McFadden

COL, IN

Commanding

- j. (U) Flight Information: None
- k. (U) Safety: None
- 1. (U) Headquarters Commendant: Nono

9 Incl d Incl - as

是一个时间,我们就是这个时间,也是是这个时间,也不是是一个时间,这一个时间,我们也是一个时间,也是一个时间,也是一个时间,也是一个时间,他们也是一个时间,他们也

9 Incl - 120th AHC ORLL Incl 2 - 9 wd Hq, DA

ILSTRIBUTION:

CG, USARPAC, ATTN: GPOP-DT

CG, USARV, ATTN: AVHGC-DST

CG, lat Avn Bde, ATEN: AVBA-C

AVBAGC-0 (14 May 69) 1st Ind SUBJECT: Operational Report of Headquarters 165th Aviation Froup for Period Ending 30 April 1969

DA, HEADQUARTERS; 1ST AVIATION BRIGADE, APO 96384 2 JUN 1969

THRU: Commanding General, United States Army Vietnam, ATTN: AVMIC-DST, APO 96375
Commander-in-Chief, United States Army Pacific, ATTN: GPOP-OT, APO 96558

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

This headquarters has reviewed this report, considers it to be adequate and concurs with the contents.

FOR THE CONTANDER:

DAVID R. ANDERSON

CPT. AG ASST. AG AVHGC-DST (14 May 69) 2d Ind

SUBJECT: Operational Report of Headquarters 165th Aviation Group for Period Ending 30 April 1969

HEADQUARTERS, UNITED STATES ARMY, VIETNAM, APO San Francisco 96375 13 JUH 1989

- TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96558
- 1. This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1969 from Headquarters, 165th Aviation Group.
- 2. Reference item concerning Repair of 30kW Generators, Section II, page II, paragraph e; concur. It is essential to have critical repair parts in stock; however, it is also essential to consider the density of supported equipment and the number of demands for certain repair parts that are placed on the DSU. A DSU cannot stock every repair part for every item of equipment that it supports. It can only be responsive to demand data. Units that requisition repair parts insure the availability of those parts with their requisitions. Except for continued command emphasis, no further action is required by this or higher headquarters.

FOR THE COMMANDER:

W. C. ARNIZ

CPT. AGC

Assistant Adjutant Comercia

Cy Man: 165th Avn Sp 1st Avn Bda GPOP-DT (14 May 69) 3d Ind SUBJECT: Operational Report of HQ, 165th Aviation Group for Period Ending 30 April 1969, RCS CSFOR-65 (R1)

HQ, US Army, Pacific, APO San Francisco 96558 24 JUL 69

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310

- 1. This headquarters has evaluated subject report and forwarding indorsements and concurs in the report as indorsed.
- 2. Reference paragraph 2b (1-4), Section II. This head-quarters has not received US Army, Vietnam request for additional control towers. Action will be taken to determine requirement and to supply control towers.
- 3. Reference paragraph 2e, Section II. Action is being taken to determine alleged unnecessary salvage and non-stockage of critical repair parts. Corrective action will be taken if alleged salvage and non-stockage of critical repair parts is verified.

FOR THE COMMANDER IN CHIEF:

C. L. SHORTI CPT, AGC Ass AG


Cy furn: CG USARV

DEPARTMENT OF THE ARMY HEADQUARTERS 165th AVIATION GROUP APO San Francisco 96381

AVBACD-C

14 May 1969

SUBJECT: Organization of 165th Aviation Group



* "A" Detachments

** "B" Detachments

Security Classification					
DOCUMENT CONTROL DATA - R & D					
(Security classification of title, body of abstract and indexing a					
1 ORIGINATING ACTIVITY (Composate author)		28. REPORT SECURITY CLASSIFICATION			
HQ, OACSFOR, DA, Washington, D. C. 20310	UNCLASSI	FIED			
· · · · · · · · · · · · · · · · · · ·	26. GROUP	1			
· 					
3. REPORT TITLE					
Operational Report - Lessons Learned, Hq,	65th Aviation Group				
4. DESCRIPTIVE HOTES (Type of report and inclusive dates)					
Experiences of unit engaged in counterinsu	cency operations, 1 Feb	69 to 30 Apr 69.			
9. AUTHORIS (First name, middle initial, isat name)					
CO, 165th Aviation Group		Į			
co, logen kvizeron Group					
. REPORT DATE	A. TOTAL NO. OF PAGES 76. P	13. OF REFS			
14 May 1969	21				
FA. CONTRACT OR GRANT NO.	M, ORIGINATOR'S REPORT NUMBERIS	,			
b. PROJECT NO.	692243				
s. N/A					
c. 14/A	95. OTHER HEPORT NOIS) (Any other numbers that may be assigned this report)				
		1			
d.					
10. DISTRIBUTION STATEMENT					
į					
11. SUPPLEMENTARY NOTES	12. SPONSORING MILITARY ACTIVITY				
N/A	OACSFOR, DA, Washington	n.c 20310			
N/A	oncoron, bu, masuringcon	, 5.0 20520			
13. A03 [RAC]					
•					
		i			
1					
]					
	L9				
1	L7				

DD . FORM .. 1473

UNCLASSIFIED
Security Classification